



Date: November 20, 2009

To: Tom Folkers
George Tietz

cc: Jeff Kingsley
Karen Kenagy
Russ Warner
Lucy Ziurys
Frank Demer

From: Dale Webb

Re: 12-Meter Site Safety Inspection
November 18, 2009

SUMMARY

A safety inspection was made at the 12 Meter site by Dale Webb on November 18, 2009. I am very pleased to report that all three of the safety items noted at the last inspection have been fixed or attended to properly. As always, the entire site looked clean and nice. The only new safety problem that I noticed at this inspection is that one of the emergency lights in the control room was not operating. Another item that I noticed is that there is a small amount of anti-freeze coolant leaking from one of the standby generators. This is not a safety problem, but something that should be looked at.

Inspection Results of November, 2009 are shown in bold

Item Noted	Abatement Date
Emergency light in the control room is not operating properly	

The Grinding wheel tool rest is missing from the grinder in the shop	Done
The nitrogen cylinder holder behind George's shop should be lowered about a foot to make it more secure	Done
The safety belt in the manlift should be attached to a fixed length lanyard, or the safety belt should be replaced with a harness	Done

Training needed by 12-Meter Employees	Not checked at this inspection
Forklift training	
Respirator training	
Arc Flash training	
Crane and rigging training	